

Burnaby Stone Care Ltd.



CONTACT

☎ 0161 848 8156

🌐 <http://www.burnaby.co.uk>

We have now begun cleaning and restoration works on

Marks and Spencer's flagship Liverpool City Centre Store

Works to date have included liaising with the Conservation Officer and Client to agree a scope of works with ourselves, then undertaking stone design and procurement, stone installation, re-pointing works combined with the careful cleaning of the building's ornate façade.

SERVICES

CLEANING

- JOS
- DOFF
- CHEMICAL
- POULTICE
- DUST FREE ABRASIVE
- MASON'S CLEAN
- HOT WATER VACUUM SYSTEM
- GRAFFITI REMOVAL
- GRAFFITI PROTECTION
- LOW PRESSURE WET/ DRY ABRASIVE



Existing cornice prior to preparation to receive new stonework

Stone dentils in production



Volume 1 Issue 2

ASSOCIATED SERVICES

- K-GRIP (ANTI-SLIP SYSTEM)
- ROPE ACCESS
- CAD FACILITIES
- SCAFFOLDING
- DETAILED BUILDING SURVEYS/REPORTS
- PAINT AND MORTAR ANALYSIS
- BIRD REPELLANT SYSTEMS



Works in progress —
Cornice/dentils being fixed to existing structure

Stone cornice/dentils fixed back to existing structure



.... MORE TO FOLLOW IN NEXT NEWSLETTER



Before Restoration



After Restoration

J D Wetherspoon's, The Picture House, Stafford

We have now completed restoration works to The Picture House

Works included securing existing rendered panels for stability, removing dilapidated render and renew with a specified lime render to original detailed design profiles, leaving in a near original condition.

J D Wetherspoon's, The Quayside, Newcastle

Burnaby Stone Care were asked to carry out re-pointing works to this prominent bar located on the Tyne Waterfront. However, a colony of bats living amongst the random stone walling combined with large areas of missing and defective masonry made restoration works more challenging than on first inspection. We were able to cut back by hand all friable mortar, inserting sections of locally sourced stonework to fill the many large voids whilst stabilising the wall in the process. We then re-pointed utilising a traditional lime mortar, with a brushed-back finish exposing the mortars fine aggregate.

Finally, and most importantly, we gave the bats living behind the stonework new openings in which they could enter or exit their home!



Before Restoration



After Restoration